

Dated:-05-10/2024

BUILDING SAFETY CERTIFICATE

I have personally visited & inspected the site existing School Building
“Amar Shiksha Sadan Sr. Sec. School”. situated at Sector -54
Sersa, kundle, NCR, Distt. Sonipat.

Examine the plan & Specification of building described below :-

Height of Roof, Accruals material used in its construction & the finished building & satisfied.

Work Specifications of Building: - Brick masonry work in cement mortar in foundation & super Structure, 9" Thick. Bricks wall, R.C.C. Slab Roof, C.C. Flooring, Cement Plaster both side of wall, Electricity Fitting etc.

This building structurally sound & good maintained condition at this time.

As per my observation and opinion the building is supposed to be safe stable if periodically repaired and maintained where as it does not involve the unnatural happening hence certified.

Architect 
AGASTYA NAIN
CA/2019/110563
Ph.: 9416232739